

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7984Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR VIEW MIRROR ASSY RH	CRACKED	1,728.70	1,728.70
1	OUTER MIRROR COVER RH	MISSING	141.90	141.90
1	FRT DOOR RH	BENT	1,264.00	1,264.00
1	FRT DOOR OUTER HANDLE RH	TO REPAIR SEE LABOUR	378.90	-
1	FRT DOOR INNER LOCK RH	NOT NECESSARY	688.80	-
1	ROCKER PANEL OUTER	DEFORMED	559.20	559.20
1	REAR DOOR RH	BENT	1,258.30	1,258.30
1	REAR DOOR OUTER HANDLE RH	TO REPAIR SEE LABOUR	93.90	-
1	REAR DOOR HINGE UPP RH	NOT NECESSARY	82.30	-
1	REAR DOOR HINGE LOWER RH	NOT NECESSARY	82.30	-
1	REAR DOOR CHECK RH	NOT NECESSARY	155.70	-
1	REAR FENDER RH	NOT NECESSARY	836.70	-
1	REAR WHEEL HUB CAP RH	NOT NECESSARY	177.70	-
	LESS 25% DISCOUNT		-1,862.10	-1,238.03
			5,586.30	3,714.07
	NETT ITEMS			
1	FRT DOOR COMFORT LOGO RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS STICKER RH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR OUTER HANDLE RH AND REAR DOOR OUTER HANDLE RH.		1,200.00	700.00
	SPRAY PAINTING CHARGE.		1,000.00	750.00
	WIRING CHARGE.		60.00	30.00
	TRANSFER OF DOOR (FRT & REAR).		240.00	120.00

Report Ref No. NS/INC21004683/T1tcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		60.00	40.00
			2,560.00	1,640.00
	GRAND TOTAL		8,301.30	5,493.57

RECOMMENDED COST OF LUMP SUM REPAIRS		4,400.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21004683/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.