



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3032C

| Qty                                | Description of Parts            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                 |               |                           |                   |
| 1                                  | REAR BUMPER                     | DEFORMED      | 459.40                    | 459.40            |
| 1                                  | REAR BUMPER CTR MOULDING        | DEFORMED      | 451.25                    | 451.25            |
| 1                                  | REAR BUMPER LWR MOULDING        | DEFORMED      | 155.00                    | 155.00            |
| 1                                  | REAR BUMPER FOGLAMP             | NOT NECESSARY | 201.50                    | -                 |
| 10                                 | REAR BUMPER CLIPS               | NECESSARY     | 22.00                     | 22.00             |
| 1                                  | BOOTLID EMBLEM-HYBRID           | CUT           | 24.30                     | 24.30             |
| 1                                  | BOOTLID EMBLEM-IONIQ            | NECESSARY     | 31.30                     | 31.30             |
| 1                                  | BOOTLID ASSY                    | BENT          | 2,480.40                  | 2,480.40          |
| 1                                  | SMART KEY ANTENNA               | CRACKED       | 40.50                     | 40.50             |
|                                    | LESS 20% DISCOUNT               |               | -773.13                   | -732.83           |
|                                    |                                 |               | 3,092.52                  | 2,931.32          |
| <b><u>NETT ITEMS</u></b>           |                                 |               |                           |                   |
| 1                                  | BOOTLID APPS (N)                | NECESSARY     | 30.00                     | 30.00             |
| 1                                  | BOOTLID COMFORTDELGRO (N)       | NECESSARY     | 35.00                     | 35.00             |
| 1                                  | BOOTLID 65521111 (N)            | NECESSARY     | 35.00                     | 35.00             |
| 1                                  | REAR NO PLATE W/TRIM CVR (N)    | CRACKED       | 55.00                     | 55.00             |
| 1                                  | REVERSE SENSOR (N)              | NOT WORKING   | 180.00                    | 180.00            |
| 2                                  | WINDSCREEN SEALANT @\$46.00 (N) | NECESSARY     | 92.00                     | 92.00             |
|                                    | LESS 10% DISCOUNT               |               | -42.70                    | -42.70            |
|                                    |                                 |               | 384.30                    | 384.30            |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                 |               |                           |                   |
| 1                                  | REAR BUMPER MAT (SN)            | NECESSARY     | 50.00                     | 50.00             |
|                                    |                                 |               | 50.00                     | 50.00             |
| <b><u>LABOUR</u></b>               |                                 |               |                           |                   |
|                                    | R/I REAR WINDSCREEN GLASSES.    |               | 300.00                    | 120.00            |
|                                    | PANEL BEATING.                  |               | 800.00                    | 525.00            |
|                                    | SPRAYPAINT CHARGE.              |               | 600.00                    | 500.00            |



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

| Qty  | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|----------------------|-----------|---------------------------|-------------------|
|  | R/I REVERSE SENSOR.  |           | 120.00                    | 30.00             |
|  |                      |           | 1,820.00                  | 1,175.00          |
| GRAND TOTAL  |                      |           | 5,346.82                  | 4,540.62          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION)<br>(CONFIRMED) |                      |           |                           | 3,650.00          |

Report Ref No. NS/INC21004684/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.