

NTUC - 4S
LKK -

12 K

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305463037
 REGN NO : SHC3032C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 02.04.2019
 DATE/TIME IN : 09.04.2021 14:15
 ACCIDENT DATE : 09.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	de
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	de
0003 04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	de
0004 04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	Xhr
0005 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	re
0006 04-01-0104-2270-G	BOOTLID EMBLEM-HYBRID	1	24.30	20.00	19.44	re
0007 04-01-0104-2271-G	BOOTLID EMBLEM-IONIQ	1	31.30	20.00	25.04	re
0008 28-01-9999-2025-A	BOOTLID APPS	1	30.00	10.00	27.00	re
0009 28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	35.00	10.00	31.50	re
0010 28-01-0103-0006-A	BOOTLID 65521111	1	35.00	10.00	31.50	re
0011 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	re
0012 FNPS	REAR NO.PLATE W/TRIM CVR	1 N	55.00	20.00	44.00	qva
0013 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00	an

Supp

- Bootlid - 2480.40
- Windscreen sealant - 46 x 2 - 26 Nott
- smart key antenna - 40.50.

3664.15
 20% 2931.32
 N- 431
 10% 387.90
 8N- 50
 3369.23

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC-4S

LKK-

Date: 12.04.2021

Time: 08:37:55

Page: 2

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305463037
REGN NO : SHC3032C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.04.2019
DATE/TIME IN : 09.04.2021 14:15
ACCIDENT DATE : 09.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,421.80

JOB NATURE

0000 PB PANEL BEATING
0001 SP SPRAYPAINT CHARGE
0002 L R/I REVERSE SENSOR

800.00 575

600.00 520

120.00 30.

Supp near
R/I windscreen glass - \$120

SUB-TOTAL : 1,520.00

1175

TOTAL : 2,941.80

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

4544.22

115 \$3650

3 days
#

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tay Hui 24491749

WP 12/4/21 @ 400pm

L/S Resurvey after repair

3 days

Tay Hui @ Publika.com