

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH 7077R

DOA: 08.04.2021

Date: 12/04/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
2	REAR BUMPER BRACKET LH RH		\$35.60	\$71.20
	<b>SUB TOTAL</b>			\$1,855.60
	<b>LESS 20%</b>		1356	\$371.12
	<b>DISCOUNTED TOTAL</b>		1084.80	\$1,484.48
	REAR BUMPER ADVERTISEMENT LOGO			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
1	REAR BUMPER MAT			\$50.00
	<b>Labour Charge</b>			
	WIRING CHARGE			\$60.00
	PANEL BEATING			\$350.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	<b>TOTAL LABOUR</b>			\$770.00
	<b>ESTIMATE TOTAL</b>			\$2,490.18

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495719  
 WP' 12/4/21 @ 4pm  
 2 days  
 1/5 rising after repair  
 Tanpin @ 11km from

1866.93  
 4/5 \$1500 #  
 02 days