



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104572

INV Date 30/06/2021

Reference CC4/LPC21004686/Ups3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBH 7036K
Insured Veh. YN 6033X
Claim No. 20/21/21/VC05/024445
Policy No. Z20VC05005856
Accident Date 12/04/2021
Inspection Date 13/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21004686/Ups3q2 Date: 30/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6033X	Veh. Inspected	GBH 7036K	
Policy No.	Z20VC05005856	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024445	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	13/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y70K210912	Colour	SILVER	
Odometer	175204 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	6 mm	
L/H Front Tyre	195 R15	MICHELIN	6 mm	
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/04/2021	Inspection Date	13/04/2021	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 7036K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,137.20	1,137.20
1	REAR TAILGATE SIDE LOCK LH	NOT NECESSARY	160.50	-
1	REAR TAILGATE SIDE LOCK BRACKET LH	BENT	201.60	201.60
2	REAR TAILGATE STOPPER RH/LH @\$48.60	N/S TORN	97.20	48.60
1	REAR TAILGATE STOPPER BRACKET	BENT	211.00	211.00
1	REAR TAILGATE STICKER TOYOTA	NECESSARY	223.00	175.00
1	REAR TAILGATE STICKER DYNA	NECESSARY	46.00	46.00
1	REAR TAILGATE LOWER MEMBER	BENT	485.90	485.90
5	REAR TAILLAMP RH/LH @\$293.15	CRACKED	586.30	586.30
2	REAR TAILLAMP BRACKET RH/LH @\$115.30	TO REPAIR SEE LABOUR	230.60	-
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	69.45	-
2	REAR NUMBER PLATE BRACKET	BENT	165.15	165.15
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	385.22	-
	LESS 25% DISCOUNT		-999.78	-764.19
			2,999.34	2,292.56
<u>SPECIAL NETT ITEMS</u>				
1	REAR TAILGATE STICKER 70KM/H (SN)	NECESSARY	10.00	10.00
1	REAR TAILGATE STICKER 13 PAX (SN)	NECESSARY	10.00	10.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	15.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR STEP BRACKET (SN)	BENT	180.00	100.00
			505.00	335.00
<u>LABOUR</u>				
	TO KNOCK OUT DENT ,CUT /WELD TAILGATE LOWER MEMBER AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP BRACKET RH/LH .		800.00	600.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		600.00	500.00
	TO CHECK WIRING .		30.00	20.00
	TO REMOVE ,REPLACE REVERSE SENSOR .		80.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF-KOTE.		60.00	60.00
			1,570.00	1,220.00
GRAND TOTAL			5,074.34	3,847.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/LPC21004686/Ups3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 7036K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 7036K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

