

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

M/S LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW PLAZA

SINGAPORE 189702

YN6033X

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

DATE : 13/04/2021

VEHICLE NO : GBH7036K

MAKE/MODEL : TOYOTA DYNA

ACC DATE : 12/04/2021

PARTICULAR

LIST PRICE

UNIT PRICE

SS

AMOUNT

SS

1	1	REAR TAILGATE	3enf	\$	1,137.20	\$	1,137.20	✓
2	1	REAR TAILGATE SIDE LOCK LH	an	\$	160.50	\$	160.50	x
3	1	REAR TAILGATE SIDE LOCK BRACKET LH	3enf	\$	201.60	\$	201.60	✓
4	1	REAR TAILGATE STOPPER RH / LH	n/c 7036K	\$	48.60	\$	97.20	PC
5	1	REAR TAILGATE STOPPER BRACKET	3enf	\$	211.00	\$	211.00	✓
6	1	REAR TAILGATE STICKER TOYOTA	neu	\$	223.00	\$ 175	223.00	✓
7	1	REAR TAILGATE STICKER DYNA	neu	\$	46.00	\$	46.00	✓
8	1	REAR TAILGATE LOWER MEMBER	3enf	\$	485.90	\$	485.90	✓
9	5	REAR TAILLAMP RH / LH	one	\$	293.15	\$	586.30	✓
10	2	REAR TAILLAMP BRACKET RH / LH	n	\$	115.30	\$	230.60	x
11	2	REAR NUMBER PLATE LAMP	u 7	\$	69.45	\$	69.45	x
12	2	REA NUMBER PLATE BRACKET	3enf	\$	165.15	\$	165.15	✓
13	1	REAR SPARE TYRE CARRIER	an	\$	385.22	\$	385.22	x
						\$	3,999.12	
LESS - 25%						\$	999.78	
TOTAL						\$	2,999.34	

SPECIAL NETT ITEMS

1	1	REAR TAILGATE STICKER 70 KM/H	neu	\$	10.00	✓
2	1	REAR TAILGATE STICKER 13 PAX	neu	\$	10.00	✓
3	1	REAR NUMBER PLATE	3enf	\$	25.00	15
4	1set	REVERSE SENSOR	shad	\$	280.00	200
5	1	REAR STEP BRACKET	3enf	\$	180.00	100
				\$	505.00	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD TAILGATE LOWER MEMBER AND REPLACE ACCIDENT PARTS	\$	800.00	600
2	TO SPRAY PAINTING ON ACCIDENT PORTION	\$	600.00	500
3	TO CHECK WIRING	\$	30.00	20
4	TO REMOVE, REPLACE REVERSE SENSOR	\$	80.00	40
5	TUFF - KOTE	\$	60.00	✓
		\$	1,570.00	

ESTIMATE PARTS AND LABOR GRAND TOTAL :

\$ 5,074.34

7-3056.75
25.2
2292.58
3847.58