



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4206S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT DOOR MIRROR ASSY RH	BROKEN	1,391.70	1,391.70
1	FRT DOOR RH	TO REPAIR SEE LABOUR	1,797.20	-
1	FRT DOOR OUTER MOULDING	CUT	110.10	110.10
	LESS 20% DISCOUNT		-659.80	-300.36
			2,639.20	1,201.44
	<u>NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO RH (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-	-7.50
			75.00	67.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR RH.		550.00	350.00
	SPRAY PAINTING CHARGE.		450.00	300.00
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
	WIRING CHARGE.		60.00	30.00
			1,180.00	680.00
	GRAND TOTAL		3,894.20	1,948.94
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,948.94

Report Ref No. NS/INC21004687/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.