

# TSL AUTO GARAGE

## QUOTATION/ESTIMATE

RE: REPAIR VEHICLE ON MERCEDES BENZ A200

VEHICLE NO : SLZ4401X

DATE : 13/04/2021

PARTS DESCRIPTION	QTY	UNTIL PRICE	AMOUNT
<u>LIST ITEMS</u>			
1 REAR TAILGATE	1	\$1,959.00	\$1,959.00 X
2 REAR TAILGATE LOGO	1	\$115.00	\$115.00 X
3 REAR TAILGATE EMBLEM A 200	1	\$108.00	\$108.00 X
4 REAR TAILGATE TOP LOCK	1	\$321.00	\$321.00 X
5 REAR TAILGATE INNER TRIM BOARD	1	\$587.00	\$587.00 X
6 REAR WINDSCREEN GLASS MOULDING	1	\$198.00	\$198.00 X
7 REAR WEATHER STRIPE	1	\$259.00	\$259.00 X
8 REAR BUMPER SIDE RETAINER LH	1	\$82.00	\$82.00 X
9 REAR BUMPER REINFORCEMENT	1	\$698.00	\$698.00 X
10 REAR BUMPER CENTER BRACKET	1	\$321.00	\$321.00 X
11 REAR BUMPER SPONGE	1	\$331.00	\$331.00 X
12 REAR BUMPER INNER GARNISH	1	\$314.00	\$314.00 X
13 REAR BUMPER SENSOR	232.50 2A	\$341.00	\$1,364.00 X 465
14 REAR BUMPER LOWER BRACKET LH	1	\$145.00	\$145.00 X
15 REAR BUMPER INNER LOWER BRACKET LH	1	\$114.00	\$114.00 X
16 REAR BUMPER UNDER COVER	1	\$226.00	\$226.00 X
17 REAR FENDER LH bent To Repair SN 300	1	\$1,564.00	\$1,564.00 X
18 REAR FENDER AIR VENT LH	1	\$117.00	\$117.00 X
19 REAR FENDER INNER COWLING LH	1	\$178.00	\$178.00 X
20 REAR FENDER MUDFLAP LH	1	\$112.00	\$112.00 X
21 REAR FENDER INNER GARNISH LH	1	\$98.00	\$98.00 X
22 REAR FENDER INNER PANEL LH	1	\$1,478.00	\$1,478.00 X
23 REAR FENDER WHEEL ARCH PANEL LH	1	\$1,345.00	\$1,345.00 X
24 REAR TAILLAMP LH	1	\$598.00	\$598.00 X
25 REAR TAILLAMP LOWER BRACKET LH	1	\$154.00	\$154.00 X
26 REAR END PANEL	1	\$965.00	\$965.00 X
27 REAR END PANEL TOP GARNISH	1	\$550.00	\$550.00 X
28 REAR END PANEL LOWER INNER TRIM GARNISH	1	\$459.00	\$459.00 X
29 REAR FLOOR PANEL LH	1	\$1,168.00	\$1,168.00 X
30 REAR FLOOR PANEL TOP BOARD LH	1	\$543.00	\$543.00 X
31 LH ROCKER PANEL GARNISH H	1	\$543.00	\$543.00 X
32 LH REAR SHOCK ABSORBER	645	\$756.00	\$756.00 X
33 LH REAR LOWER ARM	187.40	\$435.00	\$435.00 X
34 LH REAR UPPER ARM	355	\$423.00	\$423.00 X
35 LH REAR KUNCKLER ARM	1	\$286.00	\$286.00 X
36 LH REAR KUNCKLER ARM BEARING	1	\$163.00	\$163.00 X
37 LH REAR TRAILING ARM	1	\$145.00	\$145.00 X
38 LH REAR ROTOR DISC	1	\$226.00	\$226.00 X

SLZ4401X

PAGE 2

39 LH REAR BRAKE CALIPER	1	\$334.00	\$334.00	X
40 LH REAR BRAKE HOSE	1	\$78.00	\$78.00	X
41 LH FUEL TANK NECK	1	\$115.00	\$115.00	X

TOTAL: 3470.40 \$18,952.00 \$19,975.00

LESS 10%: 3123.36 \$1,895.20 \$1,997.50

TOTAL: 300 \$17,056.80 \$17,977.50

3423.36

## S/NETT ITEMS

1 REAR BUMPER	1286	1	\$2,483.00	\$2,483.00	del
2 REAR BUMPER DIFFUSER (CARBON FIBER)	800	1	\$2,230.00	\$2,230.00	Eng
3 REAR BUMPER SIDE GRILLE LH		1	\$160.00	\$160.00	X ny
4 LH ROCKER PANEL GARNISH (CARBON FIBER)	600	1	\$1,850.00	\$1,850.00	del
5 LH REAR TYRE		1	\$550.00	\$550.00	X ny
6 REAR TYRE RIM (1 SET)		1	\$2,800.00	\$2,800.00	cyb 1200
7 REAR BUMPER CLIPS		1	\$80.00	\$80.00	30ny
8 REAR TAILLAMP CLIPS	12		\$8.50	\$17.00	del
9 REAR END PANEL CLIPS		1	\$60.00	\$60.00	X ny
10 REAR FENDER INNER TRIM CLIPS		1	\$80.00	\$80.00	X ny
11 REAR FENDER COWLING CLIPS		1	\$60.00	\$60.00	20
12 REAR FENDER INNER GARNISH CLIPS		1	\$60.00	\$60.00	X
13 BRAKE FLUIDE		1	\$35.00	\$35.00	X
14 REAR TAILGATE INNER TRIM BOARD CLIPS		1	\$80.00	\$80.00	X
15 SEALANT		1	\$120.00	\$120.00	X
16 REAR FENDER SEALANT LH		1	\$80.00	\$80.00	X
17 REAR END PANEL SEALANT		1	\$80.00	\$80.00	X
18 LH REAR FENDER INSULATOR SEAL		1	\$150.00	\$150.00	X
19 LH REAR FLOOR PANEL INSULATOR SEAL		1	\$150.00	\$150.00	X
TOTAL: 3914.50			\$11,116.50	\$11,125.00	

TOTAL SPARE PARTS:

\$28,173.30 \$29,102.50

SLZ4401X

PAGE 3

LABOUR DESCRIPTION	AMOUNT	
1 LABOUR FOR PANEL BEATING	\$2,000.00	900
2 LABOUR FOR SPRAYPAINTING	\$1,400.00	800
3 TO RUST PROOF ON REAR ACCIDENT AREAS	\$300.00	30
4 TO APPLY TUFF COAT ON ACCIDENT AREAS	\$300.00	30
5 LABOUR FOR REMOVE AND REFIX REAR WINDSCREEN GLASS	\$150.00	X
6 LABOUR FOR REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	\$300.00	X
7 LABOUR FOR REPAIR & STRAIGHTEN REAR LH CHASSIS FRAME	\$400.00	X
8 WIRING CHECK AND RE-PROGRAMME CHECK LIGHT ON	\$400.00	30
9 WHEEL ALIGNMENT	\$200.00	80
10 TEST FOR WATER LEAKING	\$150.00	X
11 LABOUR FOR REMOVE AND RENEW LH REAR UNDER CARRIAGE	\$400.00	150
12 LABOUR FOR REMOVE AND REFIX REAR REVERSE CAMERA / RESET	\$380.00	X
13 LABOUR FOR REMOVE / RENEW AND REFIX REAR UPHOLSTERY/CARPET		
ROOF LINING TO FACILITATE THE REPAIR	\$400.00	60
		2080
<b>TOTAL LABOUR :</b>	<b>\$6,780.00</b>	
<b>TOTAL PARTS AND LABOUR :</b>	<b>\$35,882.50</b>	

Tanpin 97415744  
 - WP' 1#/4/21@ 1130  
 2/3 Resurvey after repair  
 Tanpin @ Iskandar.  
 7 days

3423.36  
 3914.50  
 2080  
 9417.82  
 1/3 \$ 7500  
 7 days

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: