

VEHICLE NO SLW 3180E HONDA SHUTTLE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Bumper		Torn 1249.00	✓ 1050
2	Front Bumper Side Retainer L/R @ \$92.50		17 185.00	X
1	Front Bumper tow cover		17 72.00	X
2	Front Bumper fog lamp	REFIX	17 0.00	X
2	Front Bumper fog lamp chrome cover	REFIX	17 0.00	X
1	Front Bumper lower centre grille	REFIX	17 0.00	X
1	RHS Headlamp HID		one 1425.00	✓ 1215
1	RHS Headlamp lower bracket support		17 112.00	X
1	RHS Front fender		DO 798.00	485.00
1	RHS Front fender inner splash shield		Torn 238.00	182.00
1	RHS Front fender HYBRID emblem		ner 92.00	80.00
1	RHS Side sill (rocker panel) rocker panel/gornish		Torn 582.00	
1	RHS Front door	REPAIR/PAINT	17 0.00	X
1	RHS Front shock absorber		8u 492.00	X
1	RHS Front lower arm		3u 382.00	
1	RHS Front tie rod		5u 178.00	X
1	RHS Front knuckle arm		3u 298.00	
1	RHS Front wheel bearing		Dyed 245.00	
			6348.00	
less 20%			1269.60	20%
			5078.40	
SPECIAL NETT ITEMS				
1SET	Front Bumper clips		ner 80.00	50
1SET	RHS Front fender inner shield clips		ner 60.00	50
1	RHS Front sports rim		Burf 980.00	400
1	Front number plate w/holder	REFIX	17 0.00	X
TOTAL PARTS			6198.40	

Not Authorized
Date

13/4/21

2/5 4200/
4 days.

who phd after repair

2-4519
20%
9-3615.20
S.N. 500.00
L-1170.00
5285.20
20%
4228.

VEHICLE NO SLW 3180E HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	1000.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (RHS front door)	800.00	600
3	To check wiring at accident damaged areas and focus headlamp beam	180.00	20
4	To provide anti-rust treatment on affected areas	150.00	30
5	To remove and replace RHS Front undercarriage parts (suspension system)	250.00	120
6	To conduct computerised wheel alignment	120.00	100
	Labour Total :	2500.00	
	TOTAL (PARTS & LABOUR):	8698.40	

NOTE: The parts listed in this PRELIMINARY ESTIMATE will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: