

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHB97115

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

PART

- 1 COVER, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 Moulding, FRONT BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 UNIT ASSY, HEADLAMP, RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
- 1 LAMP ASSY, FOG, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 LINER, FRONT FENDER, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 EMBLEM, SIDE PANEL, RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH

Special Nett

- 1 FRT BUMPER CLIP
- 1 ENGINE UNDERCOVER CLIP
- 1SET FRONT FENDER CLIP
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP
- 1 TYRE
- 1 RIM

AAD2104-042

Not Authorised

Resurvey 134 point

84683.25

SHB97115

JTDKRB3FU603092664

TOYOTA

PRIUS GEN 4

08/04/2021

AIG

13/11/2020

LIST

\$	521.00	<i>Brake</i>
\$	59.30	<i>R</i>
\$	80.10	<i>S</i>
\$	80.20	<i>L</i>
\$	30.20	<i>S</i>
\$	95.60	<i>S</i>
\$	716.60	<i>R</i>
\$	178.60	<i>S</i>
\$	2,637.60	<i>M3 cm</i>
\$	3,772.50	<i>S</i>
\$	237.10	<i>S</i>
\$	219.10	<i>S</i>
\$	202.50	<i>S</i>
\$	977.80	<i>M</i>
\$	54.60	<i>M</i>
\$	1,436.60	<i>S</i>
TOTAL	\$ 11,299.40	
25%	\$ 2,828.00	
\$	8,484.00	

\$	65.00	<i>Scin</i>
\$	60.00	<i>nn</i>
\$	65.00	<i>nn</i>
\$	75.00	<i>nn</i>
\$	90.00	<i>nn</i>
\$	350.00	<i>S</i>
\$	1,879.40	<i>S</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB97115

1 HUB CAP

AAD2104-042

\$	211.50	X
TOTAL	\$ 2,795.90	
TOTAL PARTS	\$ 9,530.50	

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	1,600.00	400
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	240.00	300
Putty And Spray Painting Of The Affected Portion.	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	1,600.00	400
To Check Electrical Lighting Concerned.	\$	170.00	200

TOTAL	\$ 4,380.00
Over All Total	\$ 15,659.90

(PART-BY-PART) Repair Days

10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and its subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: