

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMY 4843Y
TP/AIG

N/S. AIG ASIA PACIFIC INSURANCE PTE LTD

73 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 08/04/2021

TP Veh Reg No: SMQ5039M

Estimate No: ES2190434/YISHUN

Date: 10 May 2021

Policy No: 5121408745

Veh Reg No: SMY4843Y

Make/Model: HYUNDAI HYUNDAI
ACCENT (RB) 1.4 CVT

Chassis No: KMHCU41BTJU426827

Engine No: G4LCJU977029

Reg. Date: 07/05/2018

Estimate Repair Cost to Vehicle No :SMY4843Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	418.30	1 PC	418.30	✓
2 FRONT BUMPER RH SIDE RETAINER	11.00	1 PC	11.00	✓
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 FRONT RH FENDER	582.70	1 PC	582.70	✓
5 HEADLAMP RH	703.80	1 PC	703.80	✓
			1,736.80	
		Less 20%	347.36	1,389.44
Labour				
6 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,FOG LAMP,FRT RH FENDER,TO KNOCK & REPAIR FRT BUMPER REINFORCEMENT & REALIGN THE SAME	480.00	1 LA	480.00	400
7 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER	550.00	1 LA	550.00	420
8 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,060.00	1,060.00
			Total	S\$ 2,449.44
			Add GST @ 7%	171.46
			Total Amount Payable	S\$ 2,620.90

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: