

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 14/04/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMF4133M		
MODEL	: MERCEDES BENZ CLA1		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 10-Apr-21
		TIME	: 16:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

WDD1173422X672571

Asher.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,850.00	\$ 1,850.00
2	FRONT BUMPER LOGO <i>New</i>	1	\$ 130.50	\$ 130.50
3	FRONT BUMPER SIDE RETAINER <i>RH Damaged</i>	2	\$ 155.30	\$ 310.60
4	FRONT BUMPER SPONGE <i>cut</i>	1	\$ 203.00	\$ 203.00
5	FRONT BUMPER LOWER GRILLE <i>MT</i>	1	\$ 233.50	\$ 233.50
6	FRONT BUMPER TOWING COVER <i>Missing</i>	1	\$ 98.40	\$ 98.40
7	FRONT BUMPER FOGLAMP COVER <i>Delc</i>	1	\$ 250.00	\$ 250.00
8	FRONT BUMPER UNDER COVER <i>torn</i>	1	\$ 420.90	\$ 420.90
9	HEADLAMP RH <i>Cut</i>	1	\$ 3,500.00	\$ 3,500.00
10	FRONT FINDER RH <i>Repis</i>	1	\$ 980.00	\$ 980.00
11	FRONT REVERSE SENSOR <i>1 piece damaged</i>	2	\$ 280.60	\$ 561.20
12	FRONT REVERSE SENSOR GARNISH <i>Damaged</i>	1	\$ 115.70	\$ 115.70

TOTAL PRICE \$ 8,653.80

LESS 10% \$ 865.38

SUB TOTAL PRICE \$ 7,788.42

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1584.
✓
15550.
✓
35
329
2953.
x.
280-60.

5745.80
5171.22

1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
---	------------------------------------	---	----------	----------

TOTAL \$ 20.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500	
3	Tuff Coat	\$ 150.00	30	
4	WIRING CHECK	\$ 80.00	30	
5	To Re-programme.	\$ 120.00	✓	
TOTAL		\$2,350.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,808.42

TOTAL LABOUR COST : \$ 2,350.00

TOTAL REPAIR COST : \$ 10,158.42

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM

NO OF DAYS :

Adrian Ly
L/S 13/04/21.

03 Days.

total: 6271.22

L/S: 5K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5K