

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E**AAD2104-***Not Authored
L/Smp B*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

12 APR 2021**SHD813E**

WDD2120012B224840

MERCEDES

MB E 220 BLUE TEC

06/04/2021

AIG

16/12/2015

PART		LIST	
1 Rear Bumper	\$	<i>Bumper</i> 3,105.00	✓
1 Rear Bumper Lower	\$	<i>SL</i> 1,080.00	X
1 Rear Bumper Centre Pad	\$	<i>SL</i> 307.83	X
1 Rear Bumper Side Pad	\$	<i>SL</i> 186.33	X
1 Rear Bumper Tow Hook Cover	\$	<i>SL</i> 63.00	X
1 Rear Bumper Bracket	\$	<i>SL</i> 22.50	X
1 Rear Bumper Side Retainer Bracket	\$	<i>SL</i> 132.00	✓
1 Rear Bumper Inner Frame	\$	297.00	?
1 Rear Bumper Bottom Bracket	\$	<i>SL</i> 60.00	X
1 Rear Bumper Top Bracket	\$	<i>SL</i> 129.00	X
1 Rear Bumper Side Holder Bracket	\$	<i>SL</i> 135.00	X
1 Rear Bumper Inner Bracket LH	\$	<i>SL</i> 198.00	X
1 Rear Bumper Inner Bracket RH	\$	<i>SL</i> 198.00	X
1 Rear Bumper Beam	\$	1,215.00	?
1 Rear Bumper Beam Bracket LH	\$	<i>SL</i> 307.50	} X
1 Rear Bumper Beam Bracket RH	\$	<i>SL</i> 307.50	
1 Rear Bumper Bracket Centre	\$	<i>SL</i> 461.75	
1 Rear Bumper Retainer Bracket LH	\$	<i>SL</i> 202.50	
1 Rear Bumper Retainer Bracket RH	\$	<i>SL</i> 202.50	
1 Rear End Panel Outer	\$	<i>SL</i> 1,971.00	
1 Rear End Panel Inner Trim	\$	<i>SL</i> 630.00	
	\$	11,211.41	
	10% \$	1,121.14	
	\$	10,090.26	

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

\$	<i>SL</i> 700.00	X
\$	<i>SL</i> 66.00	✓

Trans-cab Auto Services Pte Ltd**AAD2104-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E

- 1SET RIM
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET FENDER CLIP
- 1 SET Rear End Panel Inner Trim Clip
- 1 SET Rear Bumper Fastener Clip

Over All Total	\$	650.00	}	X
	\$	33.00		
	\$	10.00		
	\$	20.00		
	\$	60.00		
	\$	90.00		
	\$	101.54		
TOTAL	\$	1,539.00		
TOTAL PARTS	\$	11,629.26		

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201	
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001	
To Rust-Proofing Of The Affected Areas.	\$	170.00		X
To reinstall rear bumper parking sensor.	\$	170.00	601	
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00		X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00		X
To check steering geometry and computer wheel alignment	\$	220.00		X
To Check Electrical Lighting Concerned.	\$	170.00		X
TOTAL	\$	7,070.00		

Trans-cab Auto Services Pte Ltd

AAD2104-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD813E

Over All Total \$ 28,789.53

(LUMP SUM)

Repair Days

~~20~~ DAYS

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: