



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : Auto & General Insurance (S) P L
(MOTOR CLAIM DEPARTMENT)

Email claims@gadgetdirect.com.sg

Xiao Chen

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SKG7376C Date: 14.04.2021
Vehicle Model: HYUNDAI AVANTE Reg. Date: 15.10.2020
Chassis No: KMHD841CMLU100971 D.O.A: 12.04.2021

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Rear Bumper <i>delnd</i>	1	\$ 645.30	\$ 645.30	✓
2	Rear Bumper Lower <i>delnd</i>	1	\$ 245.90	\$ 245.90	✓
3	Rear Bumper Side Retainer <i>new</i>	2	\$ 92.30	\$ 184.60	+
4	Rear Number Plate Garnish <i>new</i>	1	\$ 68.00	\$ 68.00	+
5	Rear Bumper Lower Cover LH <i>3MP</i>	1	\$ 197.80	\$ 197.80	+
6	Rear Bumper Lower Cover RH <i>3MP</i>	1	\$ 205.60	\$ 205.60	+
7	Rear Bumper Reverse Lamp LH <i>lit</i>	1	\$ 202.50	\$ 202.50	✓
8	Rear Bumper Reverse Lamp RH <i>lit</i>	1	\$ 202.50	\$ 202.50	+
9	Rear Bumper Reinforcement <i>could</i>	1	\$ 387.90	\$ 387.90	✓
10	Rear Bumper Reinforcement Bracket - Top <i>2</i>	2	\$ 64.80	\$ 129.60	+
11	Rear Bumper Reinforcement Bracket - Bottom <i>3MP</i>	3	\$ 64.80	\$ 194.40	+
12	Rear Bumper Reinforcement Bracket - Metal <i>3MP</i>	2	\$ 198.80	\$ 397.60	+

Total For List Items: \$ 3,061.70

Less Spare Parts Discount (20%): \$ 612.34

Total: \$ 2,449.36

C/F \$ 2,449.36

148160

1185.28



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 2,449.36

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Rear Number Plate W Casing <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	Rear Bumper Clips 1set <i>3 per</i>	1	\$ 30.00	\$ 30.00	✓
3	Rear Bumper Lower Clips 1set	1	\$ 30.00	\$ 30.00	✓
4	Reverse Camera 1set <i>new</i>	1	\$ 250.00	\$ 250.00	+
5	Reverse Sensor 1set <i>Damaged</i>	1	\$ 250.00	\$ 250.00	200

Total For S/N Items: \$ 610.00

260

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,000.00	\$ 1,000.00	250
2	To spray paint on affected areas	1	\$ 1,000.00	\$ 1,000.00	250
3	To apply tuff coat on affected areas	1	\$ 100.00	\$ 100.00	+
4	To remove/refix rear interior upholstery	1	\$ 100.00	\$ 100.00	+
5	To conduct wiring/wire connector check and repair	1	\$ 100.00	\$ 100.00	30
6	To replace/refix rear reverse sensor and distance setting	1	\$ 150.00	\$ 150.00	50
7	To remove/refix/replace reverse camera	1	\$ 150.00	\$ 150.00	+

Total For Labour: \$ 2,600.00

580

Grand Total: \$ 5,659.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Admin Lj
w/s 19/04/21

03 Days

total: 2025.28

r/s: 1.6K.