



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004707/Buf3e2	
			Date: 24/05/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5139X	Veh. Inspected	SLK 1186R
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/21/2026	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	14/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	KIA OPTIMA 2.0	c.c	1999
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KNAGU411MG5037380	Colour	WHITE
	Odometer	33602 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	FALKEN	5 mm
	L/H Front Tyre	225/45 R18	FALKEN	5 mm
	R/H Rear Tyre	225/45 R18	KUMHO	5 mm
	L/H Rear Tyre	225/45 R18	KUMHO	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/04/2021	Inspection Date	14/04/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	