

Hui Zhen (LKK Auto)

From: Bryan Ang (LKKAuto)
Sent: Tuesday, 27 April 2021 1:48 pm
To: Hui Zhen (LKK Auto)
Subject: RE: SLK 1186R Surveyed by Mr Lim

Hi

To remove Bootlid RH Lamp and Bootlid LH lamp.

To remove rear bumper RH side reflector.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hui Zhen (LKK Auto) <huizhen@lkkauto.com>

Sent: Monday, 26 April 2021 11:26 AM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: SLK 1186R Surveyed by Mr Lim

Dear Bryan,

For your audit.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)