

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	▼	🖨	Find Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref: CS3/MSG21004716/Evf3		
4 SHENTON WAY #21-01,SGX CENTRE 2		Date: 14/04/2021		
SINGAPORE 068807		Code: MSG		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLK 3016K	Veh. Inspected	SJM 5501B	
Policy No.	30001621713	Coverage (\$)	0.00	
Claim No.	255930	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIN B MADJ)	Assign Date	14/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/04/2021	Inspection Date	15/04/2021	
Survey held at	53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK, 408			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				