

AIG Ref: 3186539993SG

Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Fri 6/8/2021 2:43 PM

To: Goh, Jeremy <Jeremy.Goh@aig.com>

Hi Jeremy,

As spoken, there is a seal which is circle in yellow on all the off-peak vehicles.



Third party needs to break seal and reseal number plate in order to facilitate the repair work. Under LTA rules, third party needs to get approval from LTA for break seal & reseal and the fee is at \$21.40.

We hope the above clarifies.

Kindly advise mandate in Merimen. Thanks.

***Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.***

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742 3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741 4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)