



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized
11 Sep @ 7650h
Runway After Paint

MOTOR CLAIM DEPT.

T/P VEH. NO.: YQ2897E

MATE REPORT 1st QUOTATION
NER'S PARTICULAR

JOB NO:

ME: YAP BOON KHENG
DRESS:

CONTACT:

ENSE NO. SJJ1313U TRAN:
KE / MODEL: HONDA FREED
NER'S INSURER INDIA INTERNATIONAL
-CODE: TP S/A: JOEY

CHASSIS NO:
ENGINE NO:

ACCIDENT DATE: 13-Apr-21

ITEM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
REAR TAILGATE 1265.40	1	1864.00	20.00	1491.20	Y	✓
REAR TAILGATE LOGO	1	58.00	20.00	46.40	Y	✓
REAR TAILGATE EMBLEM 'FREED'	1	68.00	20.00	54.40	Y	✓
REAR TAILGATE EMBLEM 'HYBRID'	1	68.00	20.00	54.40	Y	✓
REAR TAILGATE LOCK	1	186.20	20.00	148.96	Y	✓
REAR TAILGATE RUBBER 168.50	1	187.00	20.00	149.60	Y	✓
REAR TAILGATE INNER HANDLE	1	270.90	20.00	216.72	Y	✗
REAR TAILGATE OUTER HANDLE - (chrome) 204.80	1	370.90	20.00	296.72	Y	✗ mgcm
REAR TAILGATE INNER BOARD	1	391.70	20.00	313.36	Y	✗
TAILLAMP LH 580.40	1	595.00	20.00	476.00	Y	✓
TAILLAMP RH 580.40	1	595.00	20.00	476.00	Y	✓
TAILLAMP PANEL LH ✗	1	338.50	20.00	270.80	Y	✗
TAILLAMP PANEL RH ✗	1	338.50	0.00	338.50	Y	✗
REAR END PANEL INNER GARNISH	1	98.20	20.00	78.56	Y	✓
REAR END PANEL 480	1	823.70	20.00	658.96	Y	✓
REAR BUMPER	1	759.00	20.00	607.20	Y	✓
REAR BUMPER TOWING COVER	1	68.00	20.00	54.40	Y	✗
REAR BUMPER SIDE RETAINER LH	1	45.00	20.00	36.00	Y	✗
REAR BUMPER SIDE RETAINER RH	1	45.00	20.00	36.00	Y	✗
REAR BUMPER BRACKET LH	1	48.00	20.00	38.40	Y	✓
REAR BUMPER BRACKET RH	1	48.00	20.00	38.40	Y	✓
REAR BUMPER REFLECTOR RH	1	68.00	20.00	54.40	Y	✗
REAR BUMPER REFLECTOR LH	1	68.00	20.00	54.40	Y	✗
REAR NUMBER PLATE LAMP	1	108.00	20.00	86.40	Y	✗
REAR EXHAUST SILENCER	1	820.90	20.00	656.72	Y	✗
REAR EXHAUST SILENCER MOUNTINGS	1	90.00	20.00	72.00	Y	✗
REAR EXHAUST PIPE CENTRE	1	1128.70	20.00	902.96	Y	✗
REAR EXHAUST COVER	1	280.00	20.00	224.00	Y	✗
REAR TAILGATE LAMP RH 391.60	1	490.80	20.00	392.64	Y	✓
REAR TAILGATE LAMP LH 391.60	1	490.80	20.00	392.64	Y	✓
REAR KEYLESS SENSOR	1	259.00	20.00	207.20	Y	✗
SPARE TYRE LOWER COVER	1	208.40	20.00	166.72	Y	✗
TAILGATE WINDSCREEN GLASS 1064.70 Shortland	1	1180.00	20.00	944.00	Y	✓
TAILGATE WINDSCREEN GLASS MOULDING 91.10	1	120.90	20.00	96.72	Y	✓
TAILGATE DAMPER RH	1	180.00	20.00	144.00	Y	✗
TAILGATE DAMPER LH	1	180.00	20.00	144.00	Y	✗



Asp

Fas

37	TAILGATE WIPER		401	1.00	68.00	20.00	54.40	Y	✓
38	WIPER ARM		401	1.00	150.00	20.00	120.00	Y	✗
39	WIPER MOTOR	378.80	401	1.00	660.40	20.00	528.32	Y	✓
40	THIRD BRAKE LIGHT		401	1.00	1240.00	20.00	992.00	Y	X
41	REAR FENDER INNER TRIM BOARD LH	468	468	1.00	550	236.00	188.80	Y	7 \$440 ✓
42	REAR FENDER INNER TRIM BOARD RH	468	468	1.00	550	236.00	188.80	Y	7 \$440 ✓
43	REAR FENDER INNER TOP COVER LH		401	1.00	550.00	20.00	440.00	Y	X
44	REAR FENDER INNER TOP COVER RH		401	1.00	550.00	20.00	440.00	Y	X
45	REAR FLOOR PANEL CARPET	422.50	422.50	1.00	680	20.00	544	Y	7 \$544 ✓

TOTAL (PARTS):

17010.50

13676.10

SPECIAL NETT ITEM

1	REAR WINDSCREEN SEALANT	401	1.00	50.00	0.00	50.00	Y	401
2	REAR WINDSCREEN SEAL	401	1.00	50.00	0.00	50.00	Y	301
3	REAR WINDSCREEN PRIMER AND CLEANER	401	1.00	50.00	0.00	50.00	Y	301
4	REAR WINDSCREEN SOLAR FLIM	401	1.00	280.00	0.00	280.00	Y	X
5	REVERSE CAMERA	401	1.00	680.00	0.00	680.00	Y	X
6	REVERSE SENSOR	401	1.00	280.00	0.00	280.00	Y	7 2001
7	REAR CAR CAMERA	401	1.00	480.00	0.00	480.00	Y	7 X
8	REAR BUMPER CLIPS	401	1.00	50.00	0.00	50.00	Y	✓
9	REAR END PANEL SEALANT	nec	1.00	80.00	0.00	80.00	Y	301
10	REAR NO PLATE	401	1.00	50.00	0.00	50.00	Y	451

TOTAL (PARTS):

2050.00

2050.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	1600.00	0.00	1600.00	Y	900
2	SPRAY PAINTING ON ACCIDENT AREAS	1.00	1600.00	0.00	1600.00	Y	1000
3	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	201
4	R&R INNER TRIMS, INNER GARNISH TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	801
5	R&R REVERSE CAMERA	1.00	120.00	0.00	120.00	Y	501
6	R&R REAR WINDSCREEN GLASS	1.00	150.00	0.00	150.00	Y	1201
7	R&R REAR TAILGATE COMPONENTS	1.00	120.00	1.00	120.00	Y	601
8	RESPRAY KOTE TUFF ON AFFECTED AREA	1.00	120.00	2.00	120.00	Y	601

TOTAL (LABOUR):

3910.00

3910.00

TOTAL PARTS & LABOUR

22970.50

19636.10

CESS: : \$

OF DAY :

SURVEY : BEFORE / AFTER PAINTING

T-BY-PART OR LUMP-SUM : \$

E OF SURVEY : / /

/EY BY :

TACT NC:

FAX NO :

: LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : YQ2897E

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : YAP BOON KHENG

ADDRESS :

JOB NO. :

CONTACT :

LICENSE NO. SJJ1313U TRAN:
MAKE / MODEL : HONDA FREED
OWNER'S INSURER INDIA INTERNATIONAL
JOB-CODE : TP S/A : JOEY

CHASSIS NO : GB71029929

ENGINE NO :

ACCIDENT DATE : 13-Apr-21

SUPPLEMENTARY ITEMS

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1 REAR FLOOR PANEL	1.00	1262.60	20.00	1010.08	Y	X
2 REAR END PANEL INNER	1.00	533.10	20.00	426.48	Y	X
3 SPARE TYRE PANEL INSULATOR PAD 306. Nelson	1.00	480.00	20.00	384.00	Y	✓

EXCESS : : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT NO :

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.