



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 126400367W
GST Reg No. MB 8500111 X

ESTIMATE FOR SKN1008T

Oh Yeok Pin (hu Yubin)

11 Mimosa Vale
Singapore 807932

Mobile: +6597461008

Vehicle & Document Information

WIP No 49441
Reg No/Reg Date SKN1008T / 06/01/2020
Date In/Mileage SKN1008T
Chassis No WDD1770872J1026705
Engine No 28291480162097
Make/Model MB/A 200 COMPACT SALOON
Colour/Trim 021 191 Cosmos Blac/ 041 115 ARTICOSpSea

Account No Terms Date/Time Printed CSE Operator
CS100003 Cash 13/04/2021/ 13:50 CH 371 / Go Chee Han

Description of Goods / Services

Z REQUEST

Customer Request

M BINSUN

POLICY NO/ACC DATE : DMPCSNW00002092100 // 9-4-2021
DRIVE IN/TP VEH NUMBER : 10-4-2021 // SMY2646M - UOI
DATE IN/DATE SURVEY:
DIRECT SETTLEMENT BY:

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M REAR BUMPER

M LOWER BLACK TRIM, BUMPER

M REAR BUMPER TRIM STRIP

M DISTANCE SENSOR

M RIVET FOR BUMPER

Qty	Unit Price	Disc%	Amount
960	1440.00		
600	780.00		
0.10	380.00		
	120.00		
1.00	1292.12	00.00	1292.12
1.00	208.49	00.00	208.49
1.00	148.43	00.00	148.43
2.00	182.48	00.00	364.96
10.00	4.81	00.00	48.10

Stere CLKK)
10/5/21, 10:30am

P/P

Ry Det sy

3 dys

WIL PHIL

Go Chee Han
DID : 6771 4336 HP : 9181 7117
Email : cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

7% GST on 4782.10
Nett 4,782.10
334.75

Total Payable 5,116.85

LKK Auto Consultants hence notify
the Repairer of the following:

- To reserve before after repair work
- Authorized signatory and company stamp
- To display damaged parts during resurvey

Validity of this estimate is 30 days from date of quote. This is a computer generated document, no signature is required.
Estimate is based on our initial inspection and does not include any additional parts or labour which may be
occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur,
we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring
the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg