



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004736/Kqf3e2	
			Date: 09/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 1065L	Veh. Inspected	SLA 8836E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101164/THE	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	14/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN TEANA 2.0 XL	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MNTBBAL33Z0005504	Colour	METALLIC BLACK
	Odometer	73056 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	FALKEN	7 mm
	L/H Front Tyre	215/55 R17	FALKEN	7 mm
	R/H Rear Tyre	215/55 R17	FALKEN	7 mm
	L/H Rear Tyre	215/55 R17	FALKEN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/04/2021	Inspection Date	14/04/2021
	Survey held at	RS AUTO SERVICES 160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	