



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL	Ref: CS/SMO21004736/Kqf3
50 RAFFLES PLACE #03-03	Date: 14/04/2021
SINGAPORE LAND TOWERS SINGAPORE 048623	Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1065L	Veh. Inspected	SLA 8836E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2101164/THE	Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG	Assign Date	14/04/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/04/2021	Inspection Date	14/04/2021
Survey held at	160 SIN MING DRIVE AUTOCITY # 06-01		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.