

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Billy Tan

Date: 25 May 2021

Preliminary Advice

Insured Vehicle No	: SLW5137T	Accident Date	: 11/04/2021
TP Vehicle No	: SLH9815Y	Assignment Date	: 23/04/2021
Make	: LEXUS ES250	Est. Duration of Repair	: 3
Date of Inspection	: 15/04/2021		
Inspection At	: ZENITH DANIEL AUTO SERVICES (HQ) ZENITH DANIEL AUTO SERVICES, BLK 1009 BUKIT MERAH LANE 3 #01-96 SINGAPORE 159723 SINGAPORE 159722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,997.11
Revised Amount	:S\$	3,273.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,273.13
 Lump Sum Repair	 :S\$	 2,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :