



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2106447

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/09/2021
Reference CC6/CTI21004746/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJF 5606U
Insured Veh. SJV 4067Y
Claim No. SNM21D201554/C02
Policy No. DMPCSNW00021582100
Accident Date 18/03/2021
Inspection Date 19/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21004746/Aea3q2	
			Date: 15/09/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 4067Y		Veh. Inspected	SJF 5606U
Policy No.	DMPCSNW00021582100		Coverage (\$)	0.00
Claim No.	SNM21D201554/C02		Excess (\$)	0.00
Assign From			Assign Date	19/03/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS		c.c	1497
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	MR053HY9305064622		Colour	GOLD
Odometer	223347 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		195/55 R15	YOKOHAMA	6 mm
L/H Front Tyre		195/55 R15	YOKOHAMA	6 mm
R/H Rear Tyre		195/55 R15	YOKOHAMA	6 mm
L/H Rear Tyre		195/55 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	18/03/2021		Inspection Date	19/03/2021
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 5606U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BUCKLED	766.70	589.00
1	BOOTLID LOCK	DAMAGED	100.00	100.00
1	BOOTLID W/STRIP	CUT	200.00	200.00
1	E EMBLEM	NECESSARY	40.00	40.00
1	LOGO EMBLEM	NECESSARY	50.80	50.80
1	VIOS EMBLEM	NECESSARY	48.00	48.00
2	TAILLAMP	N/S CUT	620.00	310.00
1	REAR BUMPER	DEFORMED	595.70	595.70
2	REAR BUMPER RETAINER LONG	NOT NECESSARY	200.00	-
2	REAR BUMPER RETAINER SHORT	NECESSARY	120.00	120.00
2	REAR BUMPER REFLECTOR	N/S CRACKED	251.00	125.50
4	REAR BUMPER CLIPS	NECESSARY	20.00	20.00
1	END PANEL	DENTED	645.00	645.00
1	END PANEL INNER GARNISH	DEFORMED	235.00	235.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	755.20	-
1	SPARE TYRE CARDBOARD	TORN	145.00	145.00
	LESS 25% DISCOUNT		-1,198.10	-806.00
			3,594.30	2,418.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
			300.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		1,200.00	800.00
	SPRAY PAINTING .		1,200.00	800.00
	WIRING .		30.00	30.00
	RUST PROOFING .		80.00	50.00
			2,510.00	1,680.00
	GRAND TOTAL		6,404.30	4,298.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,400.00
---	--	--	-----------------

Report Ref No. CC6/CTI21004746/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 5606U

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 5606U

RE-INSPECTION

