

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

19-Mar-21

Our ref : TP/4962/21

Zhang Hexin

7P Ching.
Asher.

RE : estimate cost for vehicle no : SJF 5606U

1 pc	bootlid <i>Buckled</i>	\$	766.70	<i>589</i>
1 pc	bootlid lock <i>Dmg</i>		100.00	
1 pc	bootlid w/strip <i>cut</i>		200.00	
1 pc	E emblem		40.00	
1 pc	logo emblem <i>3</i>		50.80	
1 pc	Vios emblem		48.00	
2 pcs	taillamp <i>LH cut</i>		620.00	<i>310</i>
1 pc	rear bumper <i>Dehnd</i>		595.70	
2 pcs	rear bumper retainer long <i>new</i>		200.00	<i>3224</i>
2 pcs	rear bumper retainer short <i>new</i>		120.00	
2 pcs	rear bumper reflector <i>LH cut</i>		251.00	<i>125.50</i>
4 pcs	rear bumper lcips <i>new</i>		20.00	
1 pc	end panel <i>dent</i>		645.00	<i>2418</i>
1 pc	end panel inner garnish <i>Dehnd</i>		235.00	
1 pc	spare tyre panel <i>new</i>		755.20	
1 pc	spare tyre cardboard <i>ton</i>		145.00	
	<i>Reverse Sensor</i>		4,792.40	
	<i>Dmg 200 (SN)</i>		1,198.10	
	less 25%		3,594.30	
Panel beating.			1,200.00	<i>80</i>
Spray painting.			1,200.00	<i>80</i>
Wiring.			30.00	
Rust proofing.			80.00	<i>50</i>
			6104.30	
			427.30	
			6531.60	

Plus 7% GST

SD : Six thousand five hundred thirty-one & cents sixty only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Adrian Cj
h/s 19/03/21
06 Days

total: 4298
h/s 3.4K
3.4K