



Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	94K

TO: AXA

Vehicle No : SBR 9981 R

Make & Model : TOYOTA NOAH

DATE: 15/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	SILDING DOOR LH <i>new & old</i>	1	\$ 1,817.40	\$ 1,817.40	1453
2	SILDING DOOR GLASS LH <i>nec</i>	1	\$ 472.00	\$ 472.00	377
3	SILDING DOOR OUTER MOULDING LH <i>new</i>	1	\$ 198.00	\$ 198.00	158
4	SILDING DOOR BLACK STICKER LH <i>new</i>	3	\$ 45.00	\$ 135.00	60
5	SILDING DOOR TOP HINGE LH X	1	\$ 144.90	\$ 144.90	
6	SILDING DOOR CENTER HINGE LH X	1	\$ 127.90	\$ 127.90	
7	SILDING DOOR BOTTOM HINGE LH X	1	\$ 127.90	\$ 127.90	
8	SILDING DOOR INNER LOCK LH X	1	\$ 466.90	\$ 466.90	
9	SILDING DOOR LOCK CATCH LH X <i>new</i>	1	\$ 56.00	\$ 56.00	
10	SILDING DOOR WEATHERSTRIP LH X	1	\$ 198.00	\$ 198.00	
11	SILDING DOOR CHANNEL LH X	1	\$ 96.00	\$ 96.00	
12	SILDING DOOR CHANNEL SEAL LH X	1	\$ 178.20	\$ 178.20	
13	SILDING DOOR REGULATOR MOTOR LH X	1	\$ 569.20	\$ 569.20	
14	SILDING DOOR REGULATOR GEAR LH X	1	\$ 316.00	\$ 316.00	
15	SILDING DOOR INNER TRIM LH X	1	\$ 758.10	\$ 758.10	
16	REAR FENDER LH X <i>new</i>	1	\$ 1,340.60	\$ 1,340.60	
17	REAR FENDER GLASS LH new X NN	1	\$ 577.00	\$ 577.00	
18	REAR FENDER GLASS MOULDING LH <i>new</i>	1	\$ 277.80	\$ 277.80	220
19	REAR FENDER GLASS INNER SEAL LH <i>new</i>	1	\$ 50.00	\$ 50.00	30
20	REAR FENDER INNER SHIELD LH X <i>new</i>	1	\$ 219.00	\$ 219.00	
21	REAR ABSORBER LH X <i>new</i>	1	\$ 546.00	\$ 546.00	
22	REAR WHEEL BEARING LH <i>photo</i>	1	\$ 560.00	\$ 560.00	448
23	REAR AXLE BEAM X	1	\$ 2,180.40	\$ 2,180.40	
24	REAR BUMPER X <i>new</i>	1	\$ 798.60	\$ 798.60	
25	REAR BUMPER SIDE RETAINER X	2	\$ 92.00	\$ 184.00	
26	SIDE SKIRT LH <i>new</i>	1	\$ 972.00	\$ 972.00	770

	3516	Subtotal :	\$ 13,366.90
		Less 25%	\$ 3,341.73
	2637	Parts Total :	\$ 10,025.18

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	SPORT RIM / CA	1	\$ 1,200.00	\$ 1,200.00 300
2	SPORT TYRE X	1	\$ 550.00	\$ 550.00
3	REAR DOOR INNER TRIM CLIP SET X	1	\$ 50.00	\$ 50.00
4	REAR FENDER SEALANT X	1	\$ 80.00	\$ 80.00
5	REAR FENDER GLASS SEALANT X	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER SHIELD CLIP SET X	1	\$ 40.00	\$ 40.00
7	REAR BUMPER CLIP SET X	1	\$ 50.00	\$ 50.00
8	SIDE SKIRT CLIP SET / mbl	1	\$ 40.00	\$ 40.00 20
				\$ 2,090.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	400 \$ 1,600.00
TO SPRAY PAINT AFFECTED AREA	600 \$ 1,400.00
TO PERFORM LIGHTING & WIRING CHECK	any X \$ 150.00
TO APPLY ANTI-RUST & TUFF KOTE	any X \$ 250.00
REMOVE AND INSTALL SILDING DOOR PART	60 \$ 180.00
REMOVE AND INSTALL REAR FENDER GLASS	80 60 \$ 250.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	60 \$ 450.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	50 \$ 600.00
TO JACK AND REALIGNMENT CAR BODY BACK TO MANUFACTURING SPECIFICATION	any X \$ 300.00
TO REPROGRAM, RESET AND CHECK ABS SYSTEM FUCTION	40 X \$ 600.00
TO CHECK FOUR WHEEL ALIGNMENT	60 \$ 100.00
	1350

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LABOUR TOTAL \$ 5,880.00

Total Parts Cost	\$ 12,115.18
Total Labour Cost	\$ 5,880.00
Total Repair Cost	\$ 17,995.18

4307

-20%: 3450

5 Days