

TPAXA. Smu4079H 2010 Sept.

Xiao Tong Mercedes Benz C180 1796 cc

WDD2040492A404036.

Rear Bumper	Distal	1350	✓
Rear Bumper Clips.	mm	50(SN)	✓
Rear Bumper Side Holder	x 02	75x2=150	x
Rear Bumper Reinforcement.	Distal	707	✓
Rear Bumper Lower Spoiler	Distal	1300(SN) 1000(SN)	
Reverse Sensor	x 03. 2 pieces dend	250x3=750.500	
Rear End Panel	Reps	923.	x
Rear End Panel Top Garnish.	mm	165	x
Rear End Panel Top Garnish Clips.	mm	20(SN)	x
Tailump RH.	could	542	-
Tailump lower Bracket RH.		=	
Bootlid	Reps	1735	+
Bootlid Lock	mm	340	+
Bootlid Weathersripe.	mm	198	+

SMU 4079H.

Mercedes Benz Logo. } 58 ✓

AMG Emblem. } Mc 80(SN) ✓

Rees Exhaust Pipe. Best ~~2520(SN)~~ 1400(SN)

Rees Exhaust Mounting. torn 89. ✓

Panel Beating. ~~1000~~ 500

Spray Painting. ~~1000~~ 700

Wiring. ~~50~~ 30

To remove upholstery. ~~150~~ 40

To remove reverse sensor ~~100~~ 60

To spray full coat. ~~150~~ 40

To remove exhaust pipe. ~~250~~ 120

To transfer bootlid fittings. 150. X

List: 3246

Labour: 1490

Less 10%: 2921.40

Total: 6861.40

S.N: 2450

c/s: 5.5K

050 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: