

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Apr 2021)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC3023D/13/04/2021 10:52
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Bumper, front	20.00	0.00	de *430.90 FL
2	1		*FRT BUMPER CLIP SET	20.00	0.00	rec *22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	20.00	0.00	de *28.00 FL
4	1		*FRT BUMPER SIDE BRACKET TOP LH	20.00	0.00	X *35.00 FL
5	1		*HEADLAMP LH	20.00	0.00	X *1,993.65 FL
Sub Total (S\$)						2,509.55
- List Item Discount on L Items (S\$)						501.91
Total Parts (S\$)						2,007.64

ComfortDelGro Engineering Pte Ltd/SHC3023D/13/04/2021 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

452.90
362.32.

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 450.00
2	SPRAY PAINTING	New	250 300.00
3	TUFF KOTE	New	ny. X 50.00
4	CHECK WIRING	New	50 60.00
Gross Labour Cost (S\$)			630 860.00

ComfortDelGro Engineering Pte Ltd/SHC3023D/13/04/2021 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

\$1003.22
2 days #

Tanphai 92495749

WP 13/4/21 C/30

2 days p/p Resurvey before paint

Tanphai C/30 info. on

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: