

## Veron Chen (LKKAuto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Wednesday, 1 December 2021 9:36 AM  
**To:** Veron Chen (LKKAuto)  
**Subject:** RE: SLM 868C ---CS1/ASM21004752/Vvy3

Dear Veron,

Audit check done for SLM868C, found front bumper price need verification and surveyor marking need to review. I already informed Thevan.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 30 November, 2021 5:51 PM  
**To:** Simon Ho (LKKAuto)  
**Subject:** SLM 868C ---CS1/ASM21004752/Vvy3

Dear Simon

File for audit check.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)