



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR21004754/Kuf3e2 Date: 01/10/2021 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SG 3030G	<b>Veh. Inspected</b>	SKS 378E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	BUS/04/21/1026	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	15/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	HONDA EDIX (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	BE31203634	<b>Colour</b>	METALLIC WHITE
<b>Odometer</b>	238333 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/55 R16	PIRELLI	5 mm
<b>L/H Front Tyre</b>	205/55 R16	PIRELLI	5 mm
<b>R/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	205/55 R16	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	04/04/2021	<b>Inspection Date</b>	03/08/2021
<b>Survey held at</b>	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	