

S&R Take  
#(2/18)



**K. Kim Hin** AUTO PTE LTD

CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SG 3030 G  
Accident Date : 04-Apr-2021

No. : 31749  
Date : 08-Apr-2021

Our Ref : 021127 (SMRT) / QUEK

PAGE : 1

IVAN GOH KIM LENG (MR)  
Singapore

*Not Authorised  
L1 Pay \$1200/hr  
Recovery After Paint  
4 days*

ESTIMATED COST OF REPAIR FOR HONDA EDIX 2.0X (A) (2008) SKS378E

1 pc LH wing mirror assy		CM	680.00	✓
1 pc LH front fender		R	550.00	✓
1 pc LH front fender inner shield		R	100.00	✓
8 pcs LH front fender inner shield clips	@ S\$ 3.50	R	28.00	✓
1 pc LH front bumper side retainer		R	30.00	X
			1,388.00	
	Less 20% :		-277.60	
			1,110.40	
1 pc LH front door company advertisement sticker		(Att) R	400.00	sn 600/hr
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			650.00	250/
To putty and respray on affected portions.			950.00	660/
	Total :		S\$ 3,110.40	

Singapore Dollars Three Thousand One Hundred and Ten and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

T.B.F. (S)

TOTAL