



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21002968/T1qf3e2-1	
			Date: 23/04/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9998G	Veh. Inspected	SKZ 8576K	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024294	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NRE1610010108	Colour	WHITE	
Odometer	293405 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	KAPSEN	6 mm	
L/H Front Tyre	185/60 R15	KAPSEN	6 mm	
R/H Rear Tyre	185/60 R15	KAPSEN	6 mm	
L/H Rear Tyre	185/60 R15	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/03/2021	Inspection Date	08/03/2021	
Survey held at	FREESION AUTODRIVE 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #03-33 SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	