



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004756/Quf3n2	
			Date: 12/05/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 5802H	Veh. Inspected	SJG 4927U
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/04/21/7011	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	15/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053HY9305069352	Colour	SILVER
	Odometer	240332 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	WINDFORCE	6 mm
	L/H Front Tyre	195/55 R15	WINDFORCE	6 mm
	R/H Rear Tyre	195/55 R15	WINDFORCE	6 mm
	L/H Rear Tyre	195/55 R15	WINDFORCE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/04/2021	Inspection Date	15/04/2021
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	