



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

Estimation

Date: 15/4/2021

Vehicle: sjc4927u **STG49274**

Make / Model: TOYOTA VIOS

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / CH4	1	\$ 598.00	\$ 598.00 468-
2	FRONT BUMPER SIDE RETAINER LH / Bn	1	\$ 45.00	\$ 45.00 ✓
3	FRONT BUMPER FOGLAMP CHROME LH / R/SN	1	\$ 159.00	\$ 159.00 108
4	FRONT BUMPER FOGLAMP LH X SVC	1	\$ 321.00	\$ 321.00 X
5	HEADLAMP LH / SK	1	\$ 698.00	\$ 698.00 580
6	HEADLAMP TOP PANEL LH X SVC	1	\$ 212.00	\$ 212.00 X
7	FRONT FENDER LH / PD	1	\$ 498.00	\$ 498.00 ✓
8	FRONT FENDER TOP GARNISH LH X SVC	1	\$ 49.00	\$ 49.00 X
9	FRONT FENDER INNER COWLING LH / pet.	1	\$ 159.00	\$ 159.00 110
10	SIDE MIRROR LH X SVC	1	\$ 587.00	\$ 587.00 X
11	FRONT DOOR LH X SVC	1	\$ 869.40	\$ 869.40 X
12	FRONT DOOR WEATHERSTRIP LH X SVC	1	\$ 198.20	\$ 198.20 X
13	FRONT WHEEL HUP LH X SVC	1	\$ 395.00	\$ 395.00 X
14	FRONT KNUCKLE ARM LH / B7	1	\$ 376.20	\$ 376.20 ✓
15	FRONT KNUCKLE ARM BEARING LH / Jupa	1	\$ 179.50	\$ 179.50 131.40
16	FRONT LOWER ARM LH X SVC	1	\$ 394.70	\$ 394.70 X
17	FRONT STABILIZER BAR LH X SVC	1	\$ 498.20	\$ 498.20 X
18	FRONT SHOCK ABSORBER LH X SVC	1	\$ 412.30	\$ 412.30 X
19	FRONT ABS SENSOR LH X SVC	1	\$ 212.00	\$ 212.00 X
				\$ 6,861.50 2,316.60
			Less 25%	\$ 1,715.38 -25%
			Total	\$ 5,146.13 1,737.45

S/Nett items:				
1	FRONT BUMPER CLIPS SET / Npc	1	\$ 50.00	\$ 50.00 30
2	FRONT FENDER SEALANT / Npc	1	\$ 80.00	\$ 80.00 30
3	FRONT FENDER COWLING CLIPS SET / Nec.	1	\$ 50.00	\$ 50.00 20
4	FRONT DOOR INNER TRIM CLIPS SET X SVC	1	\$ 50.00	\$ 50.00 X
5	FRONT TYRE LH X SVC	1	\$ 350.00	\$ 350.00 X
6	FRONT SPORTS RIM LH / CH4	1	\$ 800.00	\$ 800.00 300
7	BRAKE OIL X SVC	1	\$ 30.00	\$ 30.00 X
				\$ 3,060.00 380
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 400
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00 400
3	TO CHECK ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00 30
4	REMOVE AND REPAIR FRONT UNDER CARRIAGE	1	\$ 350.00	\$ 350.00 100

5	REFOCUS HEADLAMP BEAM	1	\$ 80.00	\$ 80.00
6	CONDUCT FULL WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
				\$ 2,500.00
			Parts Replacement Amount	\$ 8,206.13
			Total Amount for Labour	\$ 2,500.00
			Total Amount	\$ 10,706.13

60
30
1,020.

Repair day 3 days

L/S

After paint photo

Sin Pin CLKK

15/04/2021

TP with photo

1,737.45

380

1,020

3,137.45

-20%

2,509.96

L/S

\$2,500

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: