

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC3703A

Date: 13/04/2021

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <del>X</del> R - <del>ND</del>			\$459.40
10	REAR BUMPER CLIPS / <del>APC</del>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY ✓ <del>OR</del>			\$451.25
1	REAR BUMPER BRACKET LH X <del>nn</del>			\$55.80
1	REAR BUMPER REINFORCEMENT <del>X</del> <del>nn</del>			\$394.80
1	REAR BUMPER LOWER CTR MOULDING / <del>CUT</del>			\$155.00
1	REAR BUMPER FOG LAMP <del>X</del> / <del>BR</del>			\$201.50
1	REAR BUMPER TOWING COVER X <del>nn</del>			\$98.80
SUB TOTAL				\$1,838.55
LESS 20%				\$367.71
DISCOUNTED TOTAL				\$1,470.84
1	REAR BUMPER REVERSE SENSOR <del>nn</del>			\$180.00
				\$180.00
Labour Charge				
PANEL BEATING				
SPRAY PAINTING CHARGE				
WIRING CHARGE				
REMOVE/REFIX REVERSE SENSOR				
TOTAL LABOUR				\$830.00
ESTIMATE TOTAL				\$2,480.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve CLKK) ML PL

14/4/21, 3:00 pm

2 days

L/S

My PL dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: