



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVESINGAPORE 508969			Ref: CC3/QW21004769/T1rs3q2	
			Date: 01/06/2021	
			Code: QW007	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.		Veh. Inspected	SHD 7147Z
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	13/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMHU096344	Colour	BLUE
	Odometer	357914 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	11/04/2021	Inspection Date	13/04/2021
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	