

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7147Z

DOA: 11.04.2021

Date: 13/04/2021

Make : HYUNDAI

Insurance: QBE

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			\$1,052.20	tu
10	FRT BUMPER CLIPS			\$22.00	uq
1	FRT BUMPER BRACKET TOP RH			\$44.80	de
1	FRT FENDER RH			\$663.00	h7
1	FRT FENDER SHIELD RH			\$174.90	tu
1	HEADLAMP RH			\$1,800.00	du
1	HEADLAMP SUPPORT PANEL			\$907.40	xun
1	FRT BONNET			\$2,265.90	Ry
2	BONNET HINGE LH RH		\$126.70	\$253.40	Ry
1	FRT WINDSCREEN PILLAR OUTER RH			\$1,745.50	Ry
1	FRT DOOR RH			\$2,256.40	xun
1	FRT WHEEL HUB CAP RH			\$217.20	am
	SUB TOTAL		3974.10	\$11,402.70	
	LESS 25%		2980.57	\$2,850.68	
	DISCOUNTED TOTAL			\$8,552.03	
	FRT FENDER ADVERTISEMENT LOGO			\$100.00	ent
	FRT DOOR COMFORT LOGO RH		100	\$75.00	net
				\$175.00	net
	Labour Charge				
	PANEL BEATING		560.	\$1,200.00	
	SPRAY PAINTING CHARGE		850.	\$1,250.00	
	TRANSFER OF DOOR		1470	\$120.00	
	TUFF KOTE		30	\$60.00	
	WIRING CHARGE		30	\$60.00	
			4550.57	\$2,690.00	
	ESTIMATE TOTAL		46436.50	\$11,417.03	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 'WP' 13/4/21 @130pm
 03 days
 1/5 resurvey after repair
 Tanpin @ lkk auto