

	+
	+
	+
	1415
	385
	+
	152.
	74.
	+
	+
	—
	✓
	—
	✓
	622
	80.
	2 385
	736
	+
	+
	+
	—
	—
	+
	1215

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJA6655Y
 MODEL : MERCEDES E200
 DATE OF ACCIDENT : 14.04.21
 TIME OF ACCIDENT : 15:40HRS

26	REAR END INNER PANEL <i>Repair</i>	1	\$ 364.00	\$ 364.00	X
27	REAR END PANEL INNER GARNISH <i>new</i>	1	\$ 285.00	\$ 285.00	X
28	REAR EXHAUST PIPE <i>Dented</i>	1	\$ 1,275.00	\$ 1,275.00	✓
29	REAR EXHAUST GASKET <i>new</i>	1	\$ 87.00	\$ 87.00	-
30	REAR EXHAUST MOUNTING <i>3 new</i>	4	\$ 28.00	\$ 112.00	+
31	REAR EXHAUST INSULATOR <i>3 samples</i>	1	\$ 112.00	\$ 112.00	+

8391
7551.90

TOTAL PRICE \$ 18,962.00
 LESS 10% \$ 1,896.20
 SUB TOTAL PRICE \$ 17,065.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	30
2	REAR BUMPER BOTTOM SIDE GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	X
3	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	REAR FENDER SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
6	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	X
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	REAR FENDER AIR VENT PANEL SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	+
9	REAR WINDSCREEN INNER SEAL <i>2</i>	1	\$ 80.00	\$ 80.00	+
10	REAR WINDSCREEN SEALANT <i>3</i>	1	\$ 60.00	\$ 60.00	+
11	REAR WINDSCREEN SOLAR FILM <i>3</i>	1	\$ 550.00	\$ 550.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR END PANEL INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	X

110

TOTAL \$ 1,550.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 350.00	60
4	WIRING CHECK	\$ 380.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJA6655Y**
 MODEL : **MERCEDES E200**
 DATE OF ACCIDENT : 14.04.21
 TIME OF ACCIDENT : 15:40HRS

6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
7	TRANSFER BOOTLID MECHANISM	\$ 120.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
9	REMOVE & REFIX REAR WINDSCREEN	\$ 150.00	X
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 880.00	X

1700

TOTAL \$5,870.00

TOTAL PARTS COST : \$ 18,615.80
 TOTAL LABOUR COST : \$ 5,870.00
 TOTAL REPAIR COST : \$ 24,485.80

Adrian L
 h/s 15/04/21
 06 Days ✓

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

total 9361.80
 L/S: 7.HK ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: