

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 58139**  
Date Estimated : **13/04/2021**  
Prepared By : **Han Kwan Yong**

### - ESTIMATE REPAIR FOR -

**Ng Jui Kheng**  
**7 Pandan Valley**  
**#03-501**

**Singapore 597631**

### - ACCOUNT - 148376

**Great American Insurance Company**  
**3 Temasek Avenue**  
**#16-01 Centennial Tower**  
**Singapore 039190**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SBK1900P</b>	<b>WBA2X920307E89488</b>	<b>12/12/2019</b>	<b>216i AT</b>	<b>14757</b>

DESCRIPTION	ORIGINAL PRICE	NETT
To replace front bumper and attachments, left extension wheel housing, left support headlight arm including knock out dented area caused by the accident.	1,700.00	1,700.00
To respray front bumper.	986.00	986.00
To replace left LED technology headlight.	456.00	456.00
To remove old PDC assembly and reconnect to new bumper including conduct check for proper function.	168.00	168.00
To check electrical wiring system at the front section for proper function.	168.00	168.00
Sundries	80.00	80.00

DESCRIPTION	UNIT PRICE	QTY	NETT
LH EXTENSION WHEEL HOUSING STRUT	170.45	1.00	170.45
FRT BUMPER PRIMED PANEL (PMA)	901.75	1.00	901.75
LH SUPPORT HEADLIGHT ARM	124.05	1.00	124.05
PLAQUE 82MM	71.95	1.00	71.95
LH HEADLIGHT LED TECHNOLOGY	2,359.75	1.00	2,359.75

#### # SUPPLEMENTARY ITEMS

Total Labour :	3,558.00
Total Parts :	3,627.95
Total Labour & Parts :	7,185.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,185.95
GST @7%:	503.02
Grand Total :	7,688.97