

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004777/KPA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900010708-02
Claimant Vehicle No : GBJ5947J **Insured Vehicle No :** SCM8898U
 Date of Loss: 14/04/2021 Nature of Claim: TP Claim No: 8033555332SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ5947J**
 Make & Model: NISSAN NV200, 1.6 DX (A) Engine No: HR16143782D
 Reg. Date: 12/06/2019 (Man. Year: 2019) Chassis No: VM20133727
 Colour: Silver Odometer: 30614 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/80 R14 Rear Tyre Size: 165/80 R14
 Front Left Side: Falken 8 mm Rear Left Side: Toyo 8 mm
 Front Right Side: Falken 8 mm Rear Right Side: Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,343.72	3,096.72	247.00	7.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,730.00	430.00	19.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,503.72	4,826.72	677.00	12.30
+ GST 7.00/7.00% (S\$)	385.26	337.87	47.39	12.30
Nett Amount (S\$)	5,888.98	5,164.59	724.39	12.30
+ Car Rental (6.0 x S\$85.00/day + 7.00% GST) (S\$)		545.70		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,712.29		

INSPECTION

Date of Assignment: 15/04/2021
 Date Inspected: 16/04/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	485.90 FN	*485.90 FN
2	1		*REAR BUMPER SPONGE	Serviceable	94.00 FN	*- FN
3	6		*REAR BUMPER CLIPS	Necessary	27.00 FN	*27.00 FN
4	1		*REAR TAILGATE	Bent	1,978.40 FN	*1,978.40 FN
5	1		*TAILGATE LOGO	Necessary	69.70 FN	*69.70 FN
6	1		*TAILGATE EMBLEM (NV200)	Necessary	87.60 FN	*87.60 FN
7	1		*TAILGATE EMBLEM (VANETTE)	Necessary	69.70 FN	*69.70 FN
8	1		*TAILGATE INNER LOCK	Dented	281.10 FN	*281.10 FN
9	1		*REAR TAILGATE RUBBER	Dented / Distorted	96.40 FN	*96.40 FN
10	5		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	25.00 FN	*25.00 FN
11	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
12	1		*REAR END PANEL OUTER	Repair	162.40 FS	*- FS
13	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
14	1		*STICKER -5 PAX	Necessary	10.00 FS	*10.00 FS
15	1		*STICKER -70 KM/H	Necessary	10.00 FS	*10.00 FS
16	1		*STICKER -600 KG	Necessary	28.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	3,665.20	3,408.80
- Nett Item Discount on N Items 10.00/10.00% (S\$)	321.48	312.08
Total Parts (S\$)	3,343.72	3,096.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE ,INNER LOCK ,GARNISH ,REAR FLOOR BOARD ,CARPET ,CUT WELD & RENEW REAR END PANEL OUTER KNOCK & REPAIR REAR FLOOR BOARD PANEL & REALIGN THE SAME	New	800.00	700.00
3	PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL ,REAR END PANEL,TAILGATE & ALL REAR AFFECTED AREAS	New	900.00	700.00
4	RUSTPROOFING	New	60.00	60.00
5	TO REWRITE ADVERTISEMENT	New	280.00	150.00
Gross Labour Cost (\$\$)			2,160.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >