

# WFOOTDELGRO ENGINEERING PTE LTD.

## PAIR ESTIMATE\*

VEHICLE NO SH 8812D

12/04/21

MAKE

MODEL HYU- I40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH /RH		nn \$35.60	<del>X</del> \$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			<del>X</del> \$394.80
1	REAR PANEL GARNISH			<del>X</del> \$57.50
1	REAR END PANEL			<del>X</del> \$526.70
1	REAR PANEL LOWER			<del>X</del> \$495.50
1	BOOTLID			<del>X</del> \$2,171.90
2	REAR BUMPER REFLECTOR LH/RH		\$32.00	<del>X</del> \$64.00
			1356	\$5,137.60
			1084.80	\$1,027.52
	20.00% DISCOUNTED TOTAL			\$4,110.08
1	REAR BUMPER MAT			\$50.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REVERSE SENSOR 10% Not working			\$135.70
				\$222.13
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$600.00
	Check lighting			<del>X</del> \$50.00
	Remove/refix reverse sensor			30 - \$60.00
	Tuff Kote			\$60.00
	TOTAL LABOUR			\$1,470.00
	ESTIMATE TOTAL		1866.93 1591400 2 days	\$5,702.21
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphir 97415741  
 'WP' 13/4/21 @ 12pm  
 L/B Nemy after repair  
 Tanphir @ 11h and 10m  
 2 days