

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5555C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Apr 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS109861
Chassis No.:	JTDKB3FUX03575669
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$19,422.00
Total Rebate Amount:	\$23,172.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Apr 2021

OK

SS1E214E0006 / SMRT AUTOMOTIVE SERVICES PTE LTD
 ENTRY DATE & TIME: -
 SUBMITTED BY: [To Be Confirmed]
 VERSION: 1 (14/04/2021 13:28 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	-
Date of Accident	13/04/2021 06:40 (SGT)
Exact Location of Accident	Sembawang Way, Singapore
Additional Location Information	SEMBAWANG TOWARDS JURONG
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5555C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SMRT TAXIS PTE LTD
Company Reg No	1XXXXX369K
Email Address	TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

DRIVER

Name of Driver	KOH KWOK CHUEN
NRIC No	SXXXX441Z

(Draft)

Date Of Birth	18/07/1955
Occupation	Outdoor
Date Of Driving Pass	17/11/1975
Driving experience	45 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Other
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	NAGARAJAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG SEMBAWANG WAY TOWARDS JURONG WITH ONE PASSENGER (MALE INDIAN) ON BOARD. A VEHICLE GBG 7055K STOPPED DUE TO RED TRAFFIC LIGHT AND SUCH I STOPPED TOO. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SMZ112U HAD COLLIDED ONTO THE REAR OF MY TAXI. WHEN I ALIGHTED I REALISED THAT IT WAS A CHAIN COLLISION INVOLVING 4 VEHICLES.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMZ112U
Vehicle Manufacturer	-

(Draft)

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJT8960C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBG7055K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

WITNESS DETAILS

WITNESS 1

Name	NAGARAJAN
Phone	-
Email	-



A - 5+1B 5555C

B - SMZ 1124

C - SJT 8960C

D - GBG 7055K

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Case Details

Case Reference Number :

TAX/04/21/2034

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5555C

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-14566-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 12/04/2021 10:40 PM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ CHY
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace	✓ BT
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	✓ NEC.
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Check	✓ X
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	1	84.53	Replace	✓ BK
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	✓ BN

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	/ Neg
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	/ CNY
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	X
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	X
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	/ CNY
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ Neg
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	/ show
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	/ CNY
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check	X
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/ CNY
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	X
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Check	X

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Check	X
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	1	127.13	Replace	/Mis.
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	X
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	1	166.95	Replace	/CHA
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	697.20	Replace	/DD
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	1	270.52	Replace	/CHY
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	668.40	Replace	/CHY
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/NA
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/NA
One Time Key In	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,569.70	1,569.70	25.00	1,177.28	Replace	0	0	Not Give	X
One Time Key In	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	725.90	25.00	544.42	Replace	1	544.42	Replace	/BH
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	2	41.85	Replace	/Nec
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	/NA
One Time Key In	Main			TAILGATE TRIM, UPPER	1	50.50	50.50	25.00	37.88	Replace	0	0	Check	X
One Time Key In	Main			TAILGATE TRIM, RH	1	92.10	92.10	25.00	69.07	Replace	0	0	Check	X

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE TRIM , LH	1	92.10	92.10	25.00	69.07	Replace	0	0	Check	✓
One Time Key In	Main			TAILGATE TRIM , LOWER	1	218.50	218.50	25.00	163.88	Replace	0	0	Check	✓
One Time Key In	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Check	✓
One Time Key In	Main			TAILGATE BOARD , COVER	1	24.10	24.10	25.00	18.08	Replace	0	0	Check	✓
One Time Key In	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	118.20	25.00	88.65	Replace	0	0	Check	✓
One Time Key In	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	1	406.89	Replace	✓ J4m
One Time Key In	Main			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	1	18.98	Replace	✓ CR4
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	✓ Nec
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Check	✓
One Time Key In	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	✓
One Time Key In	Main			WIRE, TAIL GATE BACK DOOR	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	✓
One Time Key In	Main			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	✓
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ Na
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ Na
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	✓

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Check	✓ X
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	✓ CNY
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give	✓ X
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	✓ X
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	✓ X
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	✓ X
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	✓ X
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	✓ X
One Time Key In	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	✓ X

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	✓ X
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Check	✓ X
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Check	✓ X
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30	Replace	✓ / CNY
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	✓ / Nec
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Check	✓ X
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace	✓ / CNY
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ / IVA
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, ENGINE UNDER CENTER	1	94.50	94.50	25.00	70.88	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check	✓ X
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check	✓ X
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	✓ X
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	✓ X

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	✓ X
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	✓ X
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	0	Repair	✓ X R
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	✓ X
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	✓ X
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	✓ X
One Time Key In	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	0	0	Check	✓ X
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	✓ X
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	✓ X
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	✓ X
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	✓ X
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	✓ X
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	✓ X
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	✓ X
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	✓ X

Total Spare Part Cost 25,054.98

Surveyor Total 6,234.81

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,043.98

Final Sur Total 4,987.85

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	✓
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	✓
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	✓
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	✓
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	✓
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Not Give	✓
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	✓
Total Spare Part Cost									25,054.98	Surveyor Total			6,234.81	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									20,043.98	Final Sur Total			4,987.85	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	600	✓
2	Main	TO REPAIR FRONT PORTION	676.00	300	✓
Total:			1,521.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
4	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
Total:			3,888.00	900.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	TO RESPRAY REAR SPOILER	180.00	0	
6	Main	TO RESPRAY TAIL GATE	378.00	200	
7	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
8	Main	TO RESPRAY REAR PANEL	180.00	0	
9	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
10	Main	TO REPSRAY FRONT BUMPER	378.00	200	
11	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
12	Main	TO REPSRAY FRONT HOOD	378.00	200	
13	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
14	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
15	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
Total:			3,888.00	900.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100	
2	Main	TO REMOVE AND REFIX TAILGATE GLASS	120.00	60	
3	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	
7	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
8	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,415.00	455.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
11	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
Total:			1,415.00	455.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	20,043.98	4,987.85
Total Labour Cost	1,521.00	900.00
Total Spray Painting	3,888.00	900.00
Other	1,415.00	455.00
Overall Total	26,867.98	7,242.85
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	26,850.00	7,250.00
Surveyor Approved Amount		7,250.00
No of Repair Days*	13	7 
Remarks	-	L/S, after paint photo.
Surveyor Name		Sun Pin (LKK)
Signature		

Save

Clear

Survey Date

14/04/2021

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: