

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

305463968

Via Fax

BMALL

Date

15.04.71

Your Insured

SLH 87330

Time of Fax

Date of Acc

15.04.21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3456 H

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng

Tel: 6214 8355 or HP: 9824 0811

♦ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

chianglc@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH

SHD3456H

DATE 15/04/2021 CHIANG/AIG

MAKE MODEL :

I-40

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
:	FRONT BUMPER COVER			\$1,052.20
1	RADIATOR GRILLE			\$1,480.00
1	L HEAD LAMP LH			\$1,388.00
10	BUMPER CLIP			\$22.00
1	FRONT BUMPER BRACKET TOP LH/	-		\$28.60
1	FRONT BUMPER BRACKET SIDE /LH			\$28.60
	SUB TOTAL			\$3,999.40
	20.00%			\$799.88
				\$3,199.52
1	FRONT LH FENDER ADVERTISEMENT			\$100.00
	FRONT NUMBER PLATE W/HOLDER			\$55.00
				\$155.00
	Labour Charge			
	Panel Beating			\$600.00
	Spray paintimg			\$500.00
	Check Lighting			\$50.00
	TOTAL LABOUR			\$1,150.00
	ESTIMATE TOTAL			\$4,504.52
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
	be prepared after the vehicle is surveyed by a motor Survey	or appointe	ed by the insurance	company.