

## REPAIR ESTIMATE\*

VEHICLE NO SHD3456H

DATE 15/04/2021

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER	20/-	841.76	\$1,052.20
1	RADIATOR GRILLE			\$1,480.00
1	HEAD LAMP LH			\$1,388.00
10	BUMPER CLIP			\$22.00
1	FRONT BUMPER BRACKET TOP LH/			\$28.60
1	FRONT BUMPER BRACKET SIDE /LH			\$28.60
	<b>SUB TOTAL</b>		2343.76	<b>\$3,999.40</b>
	<b>20.00%</b>	20/-	187.50	<b>\$799.88</b>
				<b>\$3,199.52</b>
1	FRONT LH FENDER ADVERTISEMENT			\$100.00
1	FRONT NUMBER PLATE W/HOLDER			\$55.00
		55		\$155.00
	<b>Labour Charge</b>			
	Panel Beating		280	\$600.00
	Spray painting		250	\$500.00
	Check Lighting		530	\$50.00
	<b>TOTAL LABOUR</b>			<b>\$1,150.00</b>
	<b>ESTIMATE TOTAL</b>		45 \$1950, 2 days	<b>\$4,504.52</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpik 97495449      Wastake .  
 WP' 16/4/21 @ 4pm  
 2 days  
 4/5 Resurvey after repair  
 tanpik@khant.com

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer