



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1884Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	NOT NECESSARY	889.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NOT NECESSARY	60.80	-
1	REAR TRUNK LID LOGO (HYBRID)	NOT NECESSARY	52.40	-
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NOT NECESSARY	52.90	-
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
2	REAR BUMPER SIDE RETAINER LH/RH @\$112.70	NOT NECESSARY	225.40	-
1	REAR BUMPER UNDER COVER RH	NOT NECESSARY	232.00	-
1	REAR BUMPER TOWING COVER	DEFORMED	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
	LESS 25% DISCOUNT		-736.98	-358.68
			2,210.92	1,076.02
<b><u>NETT ITEMS</u></b>				
1	REAR TRUNK LID APPS STICKER (N)	NOT NECESSARY	40.00	-
1	REAR TRUNK LID COMFORT & TEL NO STICKER (N)	NOT NECESSARY	60.00	-
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-	-13.57
			235.70	122.13
<b><u>LABOUR</u></b>				
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.	NOT NECESSARY	90.00	-
	TUFF KOTE.	NOT NECESSARY	90.00	-
	REMOVE/REFIX REVERSE SENSOR.		90.00	30.00
			1,670.00	880.00
<b>GRAND TOTAL</b>			<b>4,116.62</b>	<b>2,078.15</b>

Report Ref No. NS/INC21004790/T1tcn2

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,078.15</b>
--	--	--	-----------------

Report Ref No. NS/INC21004790/T1tcn2



**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.