COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

Vehicle No.: SHC1884Z Make : TOYOTA Model : PRIUS

DOA :

Date :

Insurance: NTUC
MVA : CHIANG

Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE 1 REAR TRUNK LID LOGO (PRIUS)			\$889.70 \$60.80 \$53.40
	1 REAR TRUNK LID LOGO (HYBRID) 1 REAR TRUNK LID LOGO (TOYOTA STAR) 1 REAR BUMPER 1 REAR BUMPER UNDER COVER 2 REAR BUMPER SIDE RETAINER LH/RH 1 REAR BUMPER UNDER COVER RH 1 REAR BUMPER TOWING COVER 10 REAR BUMPER CLIPS 1 REAR BUMPER REINFORCEMENT		\$112.70	* \$52.40 * \$52.90 * \$458.60 * \$552.60 * \$225.40 * \$232.00 * \$232.00 * \$22.00 * \$22.00 * \$318.80
	SUB TOTAL LESS 25% DISCOUNTED TOTAL	Contains to the Contains to th	1434.70	\$2,947.90 \$736.98 \$2,210.93
	1 REAR TRUNK LID APPS STICKER 1 REAR TRUNK LID COMFORT & TEL NO. STICKER 1 REAR BUMPER REVERSE SENSOR		135.70	ペーペ \$40.0 ペペペ \$60.0 ペペ/ \$135.7 \$235.7
Green gestlandamen e	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Tuff Kote Remove/Refix Reverse Sensor	S 1885 POST STORES CONTROL CONTROL	380	350. \$800.0 500. \$600.0 ~~ \$90.0 ~~ \$90.0 30-\$90
market in the town is a fi	TOTAL LABOUR	Section 18 Acres 18	\$ 2070.15	\$1,670
	ESTIMATE TOTAL	a remote the second constitution of	\$ 2078.15 02 deys }	\$4,116

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

tanfler 974957407

UP' 13/4/2/2/2/pm

P/P Mosny before perit

tenfler e (blown forman
2 days