

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3320R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	458.60	458.60
2	REAR BUMPER SIDE RETAINER RH/LH @\$112.70	NOT NECESSARY	225.40	-
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER TOWING COVER	DEFORMED	82.70	82.70
1	REAR REINFORCEMENT	BENT	318.80	318.80
10	REAR BUMPER CLIPS @\$2.50	NECESSARY	25.00	25.00
1	REAR TRUNK HYBRID EMBLEM	NECESSARY	52.40	52.40
1	REAR TRUNK PRIUS EMBLEM	NECESSARY	52.40	52.40
1	REAR TRUNK APP COMFORT STICKER	NECESSARY	40.00	40.00
2	REAR TRUNK COMFORT & TEL NO STICKER	NECESSARY	60.00	60.00
	LESS 25% DISCOUNT		-466.98	-410.63
			1,400.92	1,231.87
	NETT ITEMS			
1	BOOTLID COMFORT & TEL NO STICKER (N)	NECESSARY	60.00	60.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	40.00	40.00
1	REAR REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-23.57	-23.57
			212.13	212.13
	<u>LABOUR</u>			
	PANEL BEATING.		875.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		90.00	30.00
			1,715.00	1,055.00
	GRAND TOTAL		3,328.05	2,499.00





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,950.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21004791/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser