

REPAIR ESTIMATE*

VEHICLE NO SH

- SHD8811 H

13/04/21

MAKE :

CHIANG / NTUC

MODEL VIANO V1

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	TAILGATE ASSY			BT \$1,975.99
1	TAILGATE TRIM		NN	X \$160.00
1	TAILGATE MERC TSTAR LOGO			del \$39.00
1	TAILGATE V220D			del \$39.00
1	TAILGATE CC EMBLEM		nn X	del \$39.00
1	TAILGATE LOCK		NN	X \$136.70
1	TAILGATE LOCK OUTER HANDLE		NN	X \$87.70
1	TAILGATE STEP GARNISH		NN	X \$52.17
2	REAR NUMBER PLATE LAMP LH/RH		XNN \$28.30	? \$56.60
1	TAIL RH LAMP ASSY			del \$622.44
2	BUMPER REFLECTOR LH & RH		XNN \$46.00	X \$92.00
1	REAR BUMPER			del \$1,372.00
2	REAR BUMPER SIDE LH & RH		CH X NN \$236.80	CH X \$473.60
	SUB TOTAL		4048.43	nn \$5,146.20
	LESS 20%		3238.74	\$1,029.24
				\$4,116.96
1	REVERSE SENSOR		no sensor	X \$388.00 NN
1	REAR NUMBER PLATE			BT \$50.00
2	SEALANT		XNN	XXXX \$46.00
	MAXICAB STICKER		80	del \$30.00
			10%-72	\$514.00
	Labour Charge			
	Panel Beating		600	\$1,080.00
	Spray Painting Charge		500	\$600.00
	Check Wiring		30	\$60.00
	Transfer Part to Tail Gate .		30	\$90.00
	Remove/refix reverse sensor		no sensor NN	X \$80.00 NN
	SUPP			\$1,910.00
	TOTAL LABOUR		1740	
	DIAGNOSTIC ERROR - \$580 NEC			
	ESTIMATE TOTAL		\$5050.74	\$6,540.96
			5 DAYS	7120.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

15/03
 Tanphat 97495749 03 days + 2 days
 - WP 13/4/21 @ 2pm PP-
 PP - Resum after repair.
 further @ 11 hours.
 205/65R16. GT Radial.

[illegible]