



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS3/AGI21001667/Eqd3e2-1 Date: 20/04/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 1282Y	Veh. Inspected	SKE 3507D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008561/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	04/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053BK4107057659	Colour	GREY	
Odometer	301453 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FIRENZA	4 mm	
L/H Front Tyre	215/60 R16	FIRENZA	4 mm	
R/H Rear Tyre	215/60 R16	FIRENZA	4 mm	
L/H Rear Tyre	215/60 R16	FIRENZA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/01/2021	Inspection Date	05/02/2021	
Survey held at	K'S PERFORMANCE 67 YUNNAN DRIVE 3 SINGAPORE 637954			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	