

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004797/ERA3Q2
Date: 20/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100436790
Claimant Vehicle No :	GBG9218U	Insured Vehicle No :	SKW8818D
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	3629708102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG9218U		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Engine No:	YD25422517A
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008558
Colour:	White	Odometer:	149516 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Double Star 5 mm	Rear Left Side:	Double Star 5 mm
Front Right Side:	Double Star 5 mm	Rear Right Side:	Double Star 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,757.52	1,172.04	2,585.48	68.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	760.00	1,140.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,657.52	1,932.04	3,725.48	65.85
Approved Total (Overridden) (S\$)		1,550.00		

(S\$)	5,657.52	1,550.00	4,107.52	72.60
+ GST 7.00/7.00% (S\$)	396.03	108.50	287.53	72.60
Nett Amount (S\$)	6,053.55	1,658.50	4,395.05	72.60
+ Loss of Use (3.0 x S\$70.00/day) (S\$)		210.00		
Nett Liability (S\$)		1,868.50		

INSPECTION

Date of Assignment: 15/04/2021

Date Inspected: 19/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)
 56 Loyang Way #06-07, Loyang Enterprise Building
 Singapore 508775

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	514.70 FL	*514.70 FL
2	2		*FRONT BUMPER SIDE RETAINER LH	Broken (1 PCS ONLY)	294.00 FL	*75.00 FL
3	1		*FRONT FOG LAMP LH	Not Necessary	343.00 FL	*- FL
4	1		*FRONT FOG LAMP GARNISH LH	Broken	117.90 FL	*117.90 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	630.00 FL	*- FL
6	1		*HEADLAMP ASSY LH	Cut	403.00 FL	*403.00 FL
7	1		*FRONT GRILLE	Not Necessary	495.00 FL	*- FL
8	1		*FRONT GRILLE LOGO	Not Necessary	115.20 FL	*- FL
9	1		*FRONT STEP PANEL GARNISH LH	Broken	125.00 FL	*125.00 FL
10	1		*FRT DOOR LH	Repair	1,015.00 FL	*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*COMPANY REGISTRATION STICKER	Necessary	30.00 FS	*30.00 FS
13	1		*FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,162.80	1,295.60
- List Item Discount on L Items 10.00/10.00% (\$)	405.28	123.56
Total Parts (\$)	3,757.52	1,172.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT & STRAIGHTEN DAMAGED PARTS ,TO REMOVE & REPLACE PARTS	New	800.00	300.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING HARNESS	New	50.00	30.00
4	TO SPRAY PAINTING FRONT BUMPER & FRONT LEFT DOOR & AFFECTED PARTS	New	800.00	400.00
5	TO TRANSFER NEW DOOR COMPONENTS TO NEW DOOR	New	150.00	0.00
Gross Labour Cost (S\$)			1,900.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >